



1/3

Step : 0.050° Cnt Time: 1.000 Sec.
Range: 4.00 - 40.00 (Deg) Step Scan Rate : 3.00 Deg./min.




Fig. 1

2/3




Fig. 2

3/3




Fig. 3